23	50	(("8,402,943") or ("5,958,217") or ("5,855,772") or ("5 093898") or ("5,025,131") or ("4,881,508") or ("4,861,966") or ("4,818,842") or ("4,713,524") or ("4,596,224") or ("4,585,924") or ("4,571,481") or ("4,539,108") or ("4,529,866") or ("4,477,715") or ("4,442,819") or ("4,406,785") or ("4,372,260") or ("4,242,564") or ("4,091,265") or ("3,235,084")).PN.	USPAT; EPO; DERWENT	2004/05/17 13:09
-	5	((heating adj element) heater) same (turn near lock)	USPAT; EPO; DERWENT	2004/05/14 14:54
-	11	((heating adj element) heater) same (twist near lock)	USPAT; EPO; DERWENT	2004/05/14 14:56
-	76	"twist lock" and (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 14:57
-	3	"twist lock" WITH (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 14:58
-	11	"twist lock" SAME (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 14:58
-	0	"Bayonette lock" SAME (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 14:58
-	4	"Bayonette" SAME (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 14:59
-	123	"quick connect" SAME (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 15:02
-	17	"quarter turn" SAME (heater "heating element")	USPAT; EPO; DERWENT	2004/05/14 15:06
-	10	4023928.URPN.	USPAT	2004/05/14 15:04
-	8	("1678778" | "1901038" | "2668993" | "3001295" | "3395972" | "3443911" | "3768982" | "3923458").PN.	USPAT	2004/05/14 15:05
-	0	"twist lock" near heater	USPAT; EPO; DERWENT	2004/05/14 15:40
-	225	(392/450, "482").CCLS.	USPAT; EPO; DERWENT	2004/05/14 15:47
-	151	(392/465).CCLS.	USPAT; EPO; DERWENT	2004/05/14 15:47
-	1	(US-6584800-$).did.	USPAT	2004/05/14 15:51
-	8	("2640138" | "4185187" | "4564962" | "5400432" | "5408578" | "5724478" | "5878192" | "6080973").PN.	USPAT	2004/05/14 15:51
-	8	("3906188" | "5054107" | "5054108" | "5271086" | "5371830" | "5408578" | "5740315" | "5872890").PN.	USPAT	2004/05/14 15:52
-	8	("2640138" | "4185187" | "4564962" | "5400432" | "5408578" | "5724478" | "5878192" | "6080973").PN.	USPAT	2004/05/14 15:56
-	13	5408578.URPN.	USPAT	2004/05/17 08:35
-	1	6205292.URPN.	USPAT	2004/05/17 07:29

| - | | 235 | ("1043922" \| "1046465" \| "1058270" \| "1281157" \| "1477602" \| "1674488" \| "1987119" \| "1992593" \| "2146402" \| "2202095" \| "2274445" \| "2426976" \| "2456343" \| "2464052" \| "2593087" \| "2593459" \| "2710909" \| "2719907" \| "2804533" \| "2889439" \| "2938992" \| "3061501" \| "3173419" \| "3191005" \| "3201738" \| "3211203" \| "3238489" \| "3296415" \| "3352999" \| "3374338" \| "3385959" \| "3496517" \| "3535494" \| "3564589" \| "3573430" \| "3597591" \| "3614386" \| "3621566" \| "3623471" \| "3648659" \| "3657516" \| "3657517" \| "D224406" \| "3678248" \| "3683361" \| "3686472" \| "3707618" \| "3725645" \| "3774299" \| "3781526" \| "3808403" \| "3831129" \| "3859504" \| "3860787" \| "3878362" \| "3888711" \| "3889047" \| "3900654" \| "3908749" \| "3927300" \| "3933550" \| "3943328" \| "3952182" \| "3968348" \| "3974358" \| "3976855" \| "3985928" \| "3987275" \| "4021642" \| "4038519" \| "4046989" \| "4058702" \| "4060710" \| "4068115" \| "4083355" \| "4094297" \| "4102256" \| "4112410" \| "4117311" \| "4119834" \| "4152578" \| "4158078" \| "4176274" \| "4186294" \| "4201184" \| "4217483" \| "4224505" \| "4233495" \| "4245149" \| "4250397" \| "4272673" \| "4294643" \| "4296311" \| "4304987" \| "4313053" \| "4313777" \| "4321296" \| "4326121" \| "4334146" \| "4337182" \| "4346277" \| "4346287" \| "4349219" \| "4354096" \| "4358552" \| "4364308" \| "4375591" \| "4387293" \| "4388607" \| "4390551" \| "4419567" \| "4429215" \| "4436988" \| "4482239" \| "4493985" \| "4501951" \| "4530521" \| "4534886" \| "4540479" \| "4606787" \| "4633063" \| "4640226" \| "4641012" \| "4658121" \| "4680446" \| "4687905" \| "4703150" \| "4707590" \| "4725717" \| "4730148" \| "4751528" \| "4756781" \| "4762980" \| "4784054" \| "4797537" \| "4845343" \| "4860434" \| "4865014" \| "4865674" \| "4866252" \| "4904845" \| "4911978" \| "4913666" \| "4927999" \| "4948948" \| "4956138" \| "4970528" \| "4972197" \| "4982064" \| "4983814" \| "4986870" \| "4993401" \| "5003693" \| "5013890" \| "5021805" \| "5023433" \| "5038458" \| "5041846" \| "5051275" \| "5066852" \| "5068518" \| "5073320" \| "5111025" \| "5113480" \| "5129033" \| "5136143" \| "5155800" \| "5162634" \| "5184969" \| "5208080" \| "5221419" \| "5221810" \| "5237155" \| "5252157" \| "5255595" \| "5255942" \| "5287123" \| "5293446" \| "5300760" \| "5302807" \| "5304778" \| "5313034" \| "5389184" \| "5397873" \| "5406316" \| "5406321" \| "5408070" \| "5453599" \| "5461408" \| "5476562" \| "5477033" \| "5497883" \| "5500667" \| "5520102" \| "5521357" \| "3268846" \| "5571435" \| "5572290" \| "5581289" \| "5582754" \| "5586214" \| "5618065" \| "5619240" \| "5625398" \| "5633668" \| "5691756" \| "5697143" \| "5703998" \| "5708251" \| "5714738" \| "5779870" \| "5780817" \| "5780820" \| "5781412" \| "5806177" \| "5811796" \| "5822675" \| "5824996" \| "5829171" \| "5835679" \| "5856650" \| "5902518" \| "5930459" \| "5940895" \| "5947012" \| "5954977" \| "5961869" \| "6056157" \| "6089406" \| "6137098" \| "6147332" \| "6147335" \| "6150635" \| "6162385" \| "6205292").PN. | USPAT | 2004/05/17 07:29 |